

Form 1069 v2018.1

T&M Request

Date: ///8/23 Requested b	v: Rob As	hton	Comp	any: <u>Precision</u>	, Pipelin	2	
Oracle Project # <i>10946494</i> 0		Ti	ask:	Maximo #_	,		
oc: WA	Site	Address: <u>82</u>	4 Clinton	Ave			
roject Type:							
☐ System Improvement	□ Main	☐ Service					
☐ Public Improvement	☐ Main	☐ Service					
☐ New Business	☐ Main	☐ Service	☐ Meter				
(Blanket	☐ Main	✓ Service	☐ Retire		,		
□ BSCI	□ Main	☐ Service					
☐ Modernization	□ Main	☐ Service					
Could not bore Service in a investigation and Finally found Contributing Factors: Out of Scope (Describe):	axiating Servi	te refind an	ł curb.				
☐ Other (Describe):							
Estimated Charge Resulting from Re				21			
3013563 - Drill rig: 2hrs 3013542 - Operator: 2hrs	3013525-3	person consti	ruction crew.	×KC3			
Did T&M Result from Change in Cons Did T&M Create a Change in Constru			Æ No L No				
Approved ByApproved By	m		/One	erations Supervisor)) Date		