

Form 1069 v2018.1

## T&M Request

Date: 5-29-24 Reques	ted by: Rob A.	shton	Compar	ny: PPL	4
5- 30-24 Oracle Project #/08576355		Task:		Maximo #	
oc: <u>WA</u>	Site				
Project Type:					
☐ System Improvement	☐ Main	☐ Service			
☐ Public Improvement	☐ Main	☐ Service			
☐ New Business	☐ Main	☐ Service	☐ Meter		
₩ Blanket	, Main	☐ Service	☐ Retire		
□ BSCI	☐ Main	☐ Service			
☐ Modernization	☐ Main	☐ Service			
Brief Description of Request:  5-29-24: Bar holed as	nd dug up hig	hest reading	· 1/2 soft su	rface, 1/2 hard surfa	ce. Shrs values were leaking. Called a later time. Shrs
CNP and instru	ited to wrap t	main valves. everything and	backfill CN	langes on 2 separate 119 to handle leaks at	values were lecking. Collect a later time. Shrs
Contributing Factors:  ☐ Out of Scope (Describe):					
Dut of scope (bescribe).			130 800 100 100 100 100 100 100 100 100 10		
☐ Change in Scope (Describe):					
Other (Describe):					
Estimated Charge Resulting from					
3013525 - Three-p	erson constr	uction crea	w-10hrs		
Did T&M Result from Change in	Construction?	O Yes	Ø No		
Did T&M Create a Change in Co	nstruction? C	Yes 💥	No		
	. 1.01 0				
Approved By	Wilhelm —		(Opera	tions Supervisor) Date	5/30/224
Approved By				Engineer) Date	