



T&M Request

Form 1069 v2018.1

Date: 5-31-24 Requested by: Rob Ashton Company: PPL

Oracle Project # 112410648 Task: _____ Maximo # _____

OC: CN Site Address: 4415 Honey Locust Ln

Project Type:

- System Improvement Main Service
- Public Improvement Main Service
- New Business Main Service Meter
- Blanket Main Service Retire
- BSCI Main Service
- Modernization Main Service

Brief Description of Request:

Bar holed hard surface. Highest reading was at valve box in road. Dug up valve box. Discovered leaking Valve R686-IN. Called CNP to grease valve. After greased, leak stopped. Re-barholed. Negative findings

Contributing Factors:

- Out of Scope (Describe):

- Change in Scope (Describe):

- Other (Describe):

Estimated Charge Resulting from Request (Labor Hours and Tooling):

3013525 - Three-person construction crew - 6hrs

Did T&M Result from Change in Construction? Yes No

Did T&M Create a Change in Construction? Yes No

Approved By J. Wilhelm (Operations Supervisor) Date 5/31/24

Approved By _____ (Project Engineer) Date _____