



T&M Request

Form 1069 v2018.1

Date: 5-14-24 Requested by: Rob Ashton Company: PPL

Oracle Project # 109438473 Task: _____ Maximo # _____

OC: FA Site Address: 344 E Whittier Ave

Project Type:

- System Improvement Main Service
- Public Improvement Main Service
- New Business Main Service Meter
- Blanket Main Service Retire
- BSCI Main Service
- Modernization Main Service

Brief Description of Request:

Above ground leak work order. Leak located on tank stop Loosened union and tightened. Leak stopped. Bar holed and soaped rest of setting. Negative findings.

Contributing Factors:

- Out of Scope (Describe):

- Change in Scope (Describe):

- Other (Describe):

Estimated Charge Resulting from Request (Labor Hours and Tooling):

3013525- 3 person construction crew - 2hrs

Did T&M Result from Change in Construction? Yes No

Did T&M Create a Change in Construction? Yes No

Approved By J. Wilhelm (Operations Supervisor) Date 5/14/24

Approved By _____ (Project Engineer) Date _____