

## Form 1069 v2018.1

## T&M Request

Date: 12 20.73 Requested b	v: PPL Tylu	Compa	ny: <u>PPL</u>		
Oracle Project #	9	Tack	Maximo #	Cp2343	57
oc: NA	Site Address:	Frankl.	RS, WCH	l	
Project Type:					
☐ System Improvement	☐ Main ☐ Ser	vice			
☐ Public Improvement	☐ Main ☐ Serv	vice			
☐ New Business	□ Main □ Serv	vice   Meter			
Blanket	□ Main 🔏 Serv	vice 🗆 Retire			
□ BSCI	□ Main □ Ser	vice /			
☐ Modernization	□ Main □ Ser	vice			
Crcw got Callob C  disgray in (m), Plant crow  Contributing Factors:	doole over after they	Shord of	<i>x y y y y y y y y y y</i>		
☐ Change in Scope (Describe): ☐ Other (Describe):					
					· ·
Estimated Charge Resulting from Re					
3013525 - 3 person	construction c	crew - 6hr	<i>S</i>		
Did T&M Result from Change in Con Did T&M Create a Change in Constru		res & No			
Approved By	.lhelm	(Оре	rations Supervisor)	Date	12/20/2024
Approved By		(Proj	ect Engineer)	Date	