

T&M Request

Form 1069 v2018.1

Date: 7/1/24 Requested by: Howard G Kessler Company: Precision Pipelines

Oracle Project # _____ Task: _____ Maxima # SDP 102557860

OC: Bairhorn Site Address: Main St, Steadville Ohio

↓ 102557860

Project Type:

- System Improvement Main Service
- Public Improvement Main Service
- New Business Main Service Meter
- Blanket Main Service Retire
- BSCI Main Service
- Modernization Main Service

Brief Description of Request:

Repairing tile that we had to break to put sewer camera
 I to get video of.
 ↳ "REPAIRING TILE THAT WE HAD TO BREAK TO PUT SEWER CAMERA
 [IN] TO GET VIDEO OF"

Contributing Factors:

Out of Scope (Describe):

Change in Scope (Describe):

Other (Describe):
 to clear right of way to be able to bore
 "BORE" ↓

Estimated Charge Resulting from Request (Labor Hours and Tooling):

3 hrs 3 man crew

Did T&M Result from Change in Construction? Yes No

Did T&M Create a Change in Construction? Yes No

Approved By J Wilhelm (Operations Supervisor) Date 7/1/2024

Approved By _____ (Project Engineer) Date _____

