



# T&M Request

Form 1069 v2018.1

Date: 2/5/24 Requested by: Brad Schuler Company: Vectren Pipeline

Oracle Project # 98785464 Task: \_\_\_\_\_ Maximo # \_\_\_\_\_

OC: DW Site Address: Intersection of Catalpa Dr and Vancouver Dr.

### Project Type:

- System Improvement       Main       Service
- Public Improvement       Main       Service
- New Business       Main       Service       Meter
- Blanket       Main       Service       Retire
- BSCI       Main       Service
- Modernization       Main       Service

### Brief Description of Request:

T&M for installing leak band on existing 4" STL LPMN.

### Contributing Factors:

#### Out of Scope (Describe):

Uncovered existing 4" STL LPMN in our bore path running north and south on Catalpa Dr, stopped work in intersection, made proper contact, cleaned main and installed leak band.

#### Change in Scope (Describe):

\_\_\_\_\_

#### Other (Describe):

PM sized hole on top of 4" STL. No other leaks found in this area.

### Estimated Charge Resulting from Request (Labor Hours and Tooling):

2-HR 3-Man Crew T&M  
1-HR Vac & Operator T&M

Did T&M Result from Change in Construction?       Yes       No

Did T&M Create a Change In Construction?       Yes       No

Approved By \_\_\_\_\_ (Operations Supervisor) Date \_\_\_\_\_

Approved By \_\_\_\_\_ (Project Engineer) Date \_\_\_\_\_