



T&M Request

Form 1069 v2018.1

Date: 6-10-24 Requested by: John Greene Company: PPL

Oracle Project # _____ Task: _____ Maximo # 112272865

OC: FA Site Address: 51 Washington St

Project Type:

- System Improvement Main Service
- Public Improvement Main Service
- New Business Main Service Meter
- Blanket Main Service Retire
- BSCI Main Service
- Modernization Main Service

Brief Description of Request:

Tried to find 4" sth to 4" plastic down by the tire shop, dug 2 holes, both in road one 6'4 one 7.5' searched both ways in hole w/ probe, not able to locate w/ locator either, Ended up calling Jim Wooten to send a locator from contractor.

Contributing Factors:

- Out of Scope (Describe):

- Change in Scope (Describe):

- Other (Describe):

Estimated Charge Resulting from Request (Labor Hours and Tooling):

8hrs 3 man crew

Did T&M Result from Change in Construction? Yes No

Did T&M Create a Change in Construction? Yes No

Approved By J. Wilhelm (Operations Supervisor) Date 6/13/2024

Approved By _____ (Project Engineer) Date _____